

**REPUBLIC CREOSOTING COMPANY**

45 34

**Mr. H. R. Horner, Indianapolis****St. Louis Park, Minn.****H. L. Dans****March 17, 1939****DRAINAGE DITCH**

US EPA RECORDS CENTER REGION 5



514464

We have your letter of March 9th, and have carefully noted your suggestions. It is our plan now to reinstall the weir just as soon as the weather permits and take a series of flow readings to determine as near as possible what capacity settling basins are required. When we do get started on this work some photographs will be made of the ditch lay out that will give you a better idea of what this situation is. We presume you have in mind that the waste water entering the settling basins be treated in order to dispose of the water soluble ingredients such as phenol, sodium sulphate, etc. We have heard nothing recently from the State Board of Health, but if they do call on us and see that we are working on the problem to correct it, they will, no doubt, be satisfied.

**Yours very truly,**

HL:lk  
cc C.B. Edwards, Indpls.

**309034**